

Circuit Diagram

WIZ-09218.MH


R410a



Updated on: 01 DEC 17

Circuit Diagram

WIZ-09218.MH INDOOR UNIT – UNITE INTERIEURE




600007000973

Circuit Diagram

WIZ-09218.MH OUTDOOR UNIT – UNITE EXTERIEURE

! WARNING
 Please don't touch any terminal when the machine is running, stopping or has been powered off for less than 30 minutes to prevent the risk of electric shock!



600007000687